


Krubbemölla byggnadsvård 2021

| | |
|---|--|
| <p>Reparation tak. Augusti 2021</p> | |
| |  A photograph showing the exterior of a traditional building with a thatched roof. The roof is made of dark, moss-covered thatch supported by wooden rafters. A section of the roof is under repair, with a wooden structure and scaffolding in place. The building has a white wall with large, irregular stone patches and a window with a blue frame. A wooden fence is in the foreground, and a brick chimney is visible on the right side of the roof. |



**Inspektion
kvarn
mekanik
210911**

En inspektion av kvarnhjul, kuggjul och kvarndamm gjordes i lördags, 210911 av experterna Gunnar Zackrisson från Svensk Byggtradition och Ingmar Melin.



Dessa menar att det inte ska vara några större problem att köra möllan redan nu under hösten. Det begränsade vattenflödet bör trots allt räcka.

